SUDAS Revision Submittal Form

Status Date:	As of 10/23/2026	**Topic:**	Partial depth patch
Manual:	Specifications	**Manual Location:**	

Requested Revision: *See attached.*


Reason for Revision: Correction from minimum 10 inch width each side of joint to 10 inch width total (both sides of joint).

Comments: Revision will match the *Concrete Pavement Preservation Guide*.


Region:	☒ Central	☒ East	☒ West
Final Comments:	None.		
Action:	☐ Deferred	☐ Not Approved	☒ Approved

Final Regional Action Summary: All 3 regions approved.


Board of Directors Action:




PCC PATCH
ACROSS JOINT




PCC PATCH
ABUTTING JOINT



SECTION A-A
(Option 1: Sawed Edges)




SECTION B-B



SECTION A-A
(Option 2: Milled Edges)

1. Vertical saw cut (typical). Apply tack coat to sides and bottom.
2. Taper the sides of the removal area 30 to 60 degrees from vertical. Apply cement grout to sides and bottom.
3. Saw and seal existing joint.
4. Extend patch limits at least 3 inches beyond distressed area.
5. When milled removal is allowed, sawed vertical edges are not required. Apply cement grout to milled area.



HMA PATCH

FIGURE 7040.104

SHEET 1 OF 1

SUDAS

REVISION
2 | 2027 Edition

7040.104

SHEET 1 of 1

SUDAS Standard Specifications

PARTIAL DEPTH PATCHES

DRAFT