

## Errata and Format Revisions

November 2025

<b>Specifications Manual Revisions</b>		
<u>Location</u>	<u>Page #</u>	<u>Revision Needed</u>
3010, 2.01, A	4	2.01, A, 1 and 2, a should reference 2.03 and 2.01, A, 3 should reference 2.04
5010, 1.08, C, 1, c and 2, c	2	Add "furnishing and installing fittings" and "anchor blocks" to the includes items.
5010, 2.05, B	7-8	Change "tensile strength" to "breaking strength"
6010, 1.08, G, 1, c	4	Delete "or intake" from includes
6010, 1.08, G, 2, c	4	Delete "or manhole" from includes
Figure 7010.101	1-8	Oval dowels accidentally removed from the figure
9040, 1.08, X, 1, c	9	Delete "concrete" before "anchor trenches"
Various sections		Will update hyperlinks in the electronic version as needed.
<b>Design Manual Revisions</b>		
<u>Location</u>	<u>Page #</u>	<u>Revision Needed</u>
2A-2, B, 1, b	1	Iowa DNR links are wrong; delete URLs from text
2B-6, Wksh 2B-6.02	5	There's no equation 8 or 9
2B-6, Wksh 2B-6.03	6	There's no equation 8 or 9; also no Table 2B-4.06
2E-2, C	6	Update links; delete URL from text
5J-1, D	12	Concrete Pavement Preservation Guide is now up to the 3rd Edition
7E-16, B, 4	3	"Entrance" needs to change to "Exit"
7G-1	1	Update reference links; delete URLs from text
9D-1, B	1	DOT research report link doesn't work; delete URLs from text
Various sections		Will update hyperlinks in the electronic version as needed.